

HP-41

Navigation Pac

Addendum Card

Module Corrections

The following corrections are for the Navigation Module, revision 1A. The revision number of the module may be examined by executing CATALOG 2.

Celestial Navigation

The declination of the star Acrux is incorrect. If this star is used, the following short program must be placed in program memory. This program will correct the problem for all programs except the STAR subroutine itself. It requires ten program registers. In order for the program to be properly stored, the Navigation Module must be plugged into the HP-41. The program can be entered with the following keystrokes:

Keystrokes

```
GTO 00
PRGM
XEQ ALPHA *STAR ALPHA
GTO 000
LBL ALPHA *STAR ALPHA
ALPHA NU* ALPHA
30
RCL 47
XEQ ALPHA INT ALPHA
X=Y?
ALPHA ASTO 47 ALPHA
SST
RTN
LBL ALPHA NU* ALPHA
ALPHA ACRUX ALPHA
30.057
STO 47
62.9275 CHS
ENTER
173.785
PRGM
```

Display

```
00 REG nnn
01 XROMT*STAR
00 REG nnn
01 LBLT*STAR
02TNU*
03 30
04 RCL 47
05 INT
06 X=Y?
07 ASTO 47
08 XROMT*STAR
09 RTN
10 LBLTNU*
11TACRUX
12 30.057
13 STO 47
14 -62.9275
15 ENTER
16 173.785
```

Now you are ready to use the star Acrux in the celestial navigation programs.