

RADIO LOG ITASCA

Date 2 JULY, 193

ENTRIES

TIME

O'HARE RM 3 C. LAST ENTRY AT	C.R.M. STANDING BY AT ALL TIMES	0658
WORKING HOWLAND I ON KEY ES FONE		0700-03
SENDING A'S ON 7500 KCS AS PER SKED		08
SHIFTED TO 3105 NW		08
NW ON 7500		12
BACK TO 3105 A'S ETC		14
CALLING EARHART ON 3105 FONE NW / NO ANS	/ SENDING A'S ON 3105 NW	15 -17
ON FNE NW	/ CUM IN PSE	23
TOD HER GA ON 3105		27
CALLING CONSTANTLY ON 3105 ON FNE ES KEY / THOMPSON RM3C ON D/F		30
EARHART ON NW SEZ RUNNING OUT OF GAS ONLY 1/2 HR LEFT CANT HR US		
AT ALL / WE HR HER AND ARE SENDING ON 3105 ES 500 SAME TIME CONSTANTLY		40
AND LISTENING IN FER HER FREQUENTLY		50
STILL SENDING ON 3105 VOICE AND KEY A'S ON KEY		55
SENDING CONSTANTLY ON 7.5 MEGS AND 3105 CALLING HER AND TELLING HER		0800
TO GA ON 3105 THAT WE HEAR HER / STOPPING FREQUENTLY TO LISTEN IN FOR		
HER / LOG AT PSN NR 2 KEEPING PERTINENT DATA		56
ON 7500 AGN / AMELIA ON AGN AT 0800 SEZ HRS US ON 7.5 MEGS GA		57
STILL SENDING ON 7500 KCS TELLING HER TO GA ON 3105 AND SENDING OUT SIGS FER		
HER TO OBSERVE BEARINGS ON / MAINTAINING LISTENING WATCH 3105 ES 7500		0908
ES 500		09
STOP SENDING TO TUNE IN SIGNALS IF ANY ON 7500 ES 3105		12
NOTHING HRD AS YET		
SENDING ON 7500 KCS TELLING HER TO ANS ON 500 OR 3105		
REPEATING ABOVE CONSTANTLY AND LISTENING ON THOSE FREQS		15
TUNING ON 6210 KCS / PSN 2 ON 3105 KCS / D/F ON 500 KCS N N N		25
CALL DE HOWLAND I ES TOLD IM GET D/F GG AT ALL COST VA/ 7500		35
CALLED EARHART ON 7500 KCS ES TOLD HER ANS ON 3105 AM TUNING NW FER HER		36
TUNING BROADLY ON 7500 / NR2 TUNING ON 3105 KCS NR3 D/F		
ON BRIDGE ON 500 KCS UNABLE READ HER/		38
STILL TUNING FER HER NOTHING HRD YET		42
KHAQQ DE NRUI / SEVERAL TIMES . WE CAN HEAR U GOOD ON 3105 SO PSE	GVE US	
YOUR PSN ES GA ON 3105 AR KKK THIS WAS SPELLED OUT IN FULL		45/48
STILL TUNING HR ON 7500 KCS NOTHING AS YET		51
SAME		54
SAME		57
SAME		1000
NRUI2 V NRUI GET D/F GG AT ANI COST/ RPTD/ BT CALLED EARHART ON		
7500 KCS AND SEZ WE HEARD U ON 3105 KEEP ON USING 3105 GO ON 3105 AR/05		
NPM NPU V NRUI AR/ NRUI V NPMK/ NMP V NRUI		
SENT NPM NR 3 ES 4 SRS 30 31 / R V NPM AT / 1020 1023		08
RECVD PRIORITY NR 3 SRS 32/ R'D AT		28
BACK ON 6201 KCS MAINTAINING LISTENING WATCH FER PLANE		30
RELEIVED BY GALTEN RM 3C. SITUATION SAME - O'HARE RM 3C.		33
WRD FM D/F/ MAN TT WGEN WAS CALLING NRUI ON 500		34
WGEN DE NRUI QRU? QSY 600 ARK / UNASRWD	REACHED	35-42
NRUI DE WGEN / WGEN DE NRUI K/ NRUI DE WGEN HAS EARHART	XXXXXXX NOW-	
LAND YET? / WGEN DE NRUI NOT YET/ R TU		43-44
LSNIN 6210 FER KHAQQ / NIL BC		45-50
SAME		53
KHAQQ DE NRUI A-S WE HEAR YOUR SIGS OK ON 3105 2 HOURS AGO GO AHEAD		
ON 3105 OR 500 KCS 7500 / UNANSWD		5

(OVER)

RADIO LOG ITASCA

Date 2 JULY 1937, 193

ENTRIES	TIME
3 W L GALTEN, RM3C ON -- CG32-1	
KHAQQ KHAQQ DENRUI NRUI GA 500 WID DASHES ON 500 K/ UNANSWD	0805-8
KHAQQ FM ITASCA DID U GET TT XMISION ON 7.5 MEGS GA ON 500 KCS	80
TT WE MAY BE ABLE TO TAKE A BEARING ON U IMPOSSIBLE TO TAKE A	
BEARING ON 3105 PLS ACKNWLGE THIS XMISION WID A3 ON 3105 GA/	
UNANSWD	11
MHAQQ DE NRUI RPTING ABEV INFO ON 7500 KCS BR/ NO ANSW	12-4
KHAQQ FM ITASCA DO U HR MY SIGS ON 7500 KCS OR 3105 KCS PLS ACKNWLGE	15
WID RECEIPT ON 3105 KCS WID A3 GA/ UNANSWD	16-8
KHAQQ DE NRUI REPTED ABEV DPE ON 7500 GA 3105 A3 AR/ UNANSWD	18
KHAQQ FM ITASCA WL U PLS Y OUR SIGS ON 7500 OR 3105 A3	19
KHAQQ UNANSWD	20-3
KHAQQ DE NRUI GA 3105 A3 KCS WID REPORT OUR SIGS	25
KHAQQ DE NRUI GA 3105 KCS WID A3 ES XMIT POSN REPT ES QSA ON OUR	27
ITASCA TO EARHART WE XMITING CONSTANTLY ON 7.5 MEGS DO U HR US	28-9
CFM RECEIPT ON 3105 WE ARE STANDING BY A3/ 3105	30-1
KHAQQ DE NRUI ANS 3105 A3 K/ UNANSWD	33
KHAQQ DE NRUI ANS 3105 KCS WITH REPORT ES POSN 7500/ UNANSWD	34-41
EARHART FM ITASCA WL U PLS CUM IN AND ANS ON 3105 WE ARE XMITING CONS-	42
TANTLY ON 7500 KCS WE DONOT HR U ON 3105 PLS ANS 3105 GA/ UNSWD	43
KHAQQ DE NRUI ANS 3105 KCS WID A3 HW OUR SIG QSA? GA/ UNANSWD	44-6
LSNIN 3105/ NIL CRM TUNIN UP T16 FER XMISION TO NMC	47
NMC V NRUI P AR.12600/ UNANSWD	48
KHAQQ TO ITASCA WE ARE ON THE LINE 157 337 WL REPT MSG WE WL REPT N ES 8	49-53
THIS ON 6210 KCS WAIT, 3105/ A3 AS (?/ KHAQQ XMISION WE ARE RUNNING ON	500
LINE LSNIN 6210 KCS/ KHAQQ DE NRUI HRD U OK ON 3105 KCS 7500	54-0907
KHAQQ DE NRUI PLS STAY ON 3105 KCS DO NOT HR U ON 6210 MAINTAIN	08
ON 3105, 7500/ UNANSWD	09-13
NIL ON 3105 OR 6210 FM KHAQQ/ KHAQQ DE NRUI ANS 3105 KCS	14
KHAQQ DE NRUI ANS 3105 KCS A3/ ANANSWD	15-33
KHAQQ DE NRUI UR SIGS OK ON 3105 GO AHEAD W TH POSN ON 3105 OR	34
KCS/ UNANSWD	35
LSNIN 3105 AND 6210 /500 KCS/NIL	36-41
KHAQQ DE NRUI ANS 3105 OR 500 UR SIGS OK ON 3105 GA WID POSN 7500	42-6
LSNIN 6210 ES 3105- NIL/500 NIL	49
LSNIN 3105, 6210, 500 AND 500 D/F- NIL	52-9
NRUI2 V NRUI PER TO REF HI FREQUENCY D/F, 7500	1002-2
KHAQQ DE NRUI GA ON 3105 KCS, 7500/ UNANSWD	03-5
NIL FROM KHAQQ/3105, 6210, 500 OR 500 D/F	AR 08-10
KHAQQ DE NRUI: XMITING DPE ON ANSWING FREQS/ WE CAN HEAR U FINE ON	12
3105 PLS GA ON 3105, 7500/ UNANSWD	14
NIL FROM KHAQQ	15-26
NIL FROM KHAQQ/ 3105, 6310, 500 OR 500 D/F	27-30
NRUI2 V NRUI: PER TO/ GET THE RDO COMPASS WRKING NOW, 7500	35
KHAQQ DE NRUI WE HEARD YOU ON 3105 KCS, ETC - 7500	
NPM NPU V NRUI V-S ZME/ NPM V NRUI INT ZCT KHAQQ INT ZCY KHAQQ	
NRUI V NPM ZZA INT FREQ AR/ 3105/ @ 20Z AR/ DID U HE KHAQQ AT	
ALL AR/ ZZA/ R THAT TO TO NPU/ R (NPM/ NRUI 12600/13380-PER TO	
NRUI V NPM AR/ NPM V NRUI R K/ B NR3 / R AS	
TO ENGAGED NPM: XMITTING P MSGS, 12600	
DC ENGAGED BON: RECIVING P, 12600/ LSNIN 3105 CONSTANTLY, NIL/BG	
BG OFF TO DC	
WGEN WGEN DE NRUI NRUI QRU IMI (OVER)	
WGEN WGEN DE NRUI QRU IMI 600 K	