

Sextant Error, in minutes of arc, Due to Sextant Tilt from Vertical

Tilt	2°	4°	6°
H _s			
5°	0.2	0.7	1.6
15	0.5	2.1	4.7
25	0.8	3.2	7.2
35	0.9	3.9	8.9
45	1.0	4.2	9.5
55	0.9	3.9	8.9
65	0.8	3.2	7.2
75	0.5	2.1	4.7
85	0.2	0.7	1.6
90	0.0	0.0	0.0